

WH12X10307
A10C2

Pressure switch connectors' position different between EMZ and Toneluck

Please notice this when changing pressure switch, the connectors location on EMZ and toneluck pressure switch are different. Please look at the pictures for detail.

Although the connectors' location changed, they are still foolproof .

Toneluck压力开关与EMZ相比,连接线束端子位置有变化.

当更换压力开关时请注意, Toneluck压力开关与EMZ压力开关的连接端子位置不同,具体细节请看右边图片说明.

虽然连接端子的位置有所变化,但是依然能够防呆.

