

WH45X10079 Basket Assembly

ATTENTION SERVICE TECH

Contents:

Basket ASM	WH45X10079	1 each
Nut M16	WH02X10211	1 each
Tub Seal	WH08X10023	1 each

1 **YOU MUST USE THE NEW NUT AND TUB SEAL**
Use the new tub seal to ensure no leaks

2 **TORQUE for the TUB Screws is 45 in lbs**
Over-Torque can Strip the Plastic Screw Bosses.
Under-Torque can cause Water Leaks.

3 When reinstalling the pulley after replacing the basket, use the new Nut to prevent the pulley from working loose from the basket shaft.
The nylon thread-locker in the Nut gets damaged when you remove the Nut.

SEATING TORQUE for the Nut M16 is 44 ft-lbs.
(approximately 1/4 turn after snug)