

<b>RPM at Free Air</b>	<b>3100</b>
<b>Static Pressure 0.1 in.</b>	<b>72</b>
<b>Static Pressure 0.2 in.</b>	<b>78</b>
<b>Static Pressure 0.3 in.</b>	<b>64</b>
<b>Static Pressure 0.4 in.</b>	<b>110</b>
<b>Static Pressure 0.5 in.</b>	<b>57</b>
<b>Static Pressure 0.6 in.</b>	<b>55</b>
<b>Static Pressure 0.7 in.</b>	<b>50</b>
<b>Static Pressure 0.8 in.</b>	<b>68</b>
<b>Static Pressure 0.9 in.</b>	<b>41</b>
<b>Static Pressure 1 in.</b>	<b>33</b>
<b>Static Pressure 1.0 in.</b>	<b>97</b>
<b>Static Pressure 1.2 in.</b>	<b>90</b>
<b>Static Pressure 1.4 in.</b>	<b>25</b>
<b>Static Pressure 1.6 in.</b>	<b>73</b>
<b>Static Pressure 2.0 in.</b>	<b>39</b>